

human settlements

Department:
Human Settlements
REPUBLIC OF SOUTH AFRICA

BENEFICIARY OCCUPANCY AUDIT PROGRESS REPORT PORT FOLIO COMMITTEE 28 JULY 2010

VISION: A NATION HOUSED IN SUSTAINABLE HUMAN SETTLEMENTS
WITH ACCESS TO SOCIO-ECONOMIC INFRASTRUCTURE

MISSION: TO ESTABLISH & FACILITATE A SUSTAINABLE PROCESS
THAT PROVIDES EQUITABLE ACCESS TO ADEQUATE HOUSING FOR ALL
WITHIN THE CONTECT OF AFFORDABILITY OF HOUSING & SERVICES
& ACCESS TO SOCIAL AMENITIES & ECONOMIC OPPORTUNITIES



BACKGROUND

- Announced during Budget Speech 2008
- Determine subsidised housing units occupied by approved beneficiaries
 - Concerned allegations subsidised houses allocated to foreigners
 - Beneficiaries not issued with title deeds
- Disparity between houses actually completed and official records
- Project outsourced to three successful service providers covering 7 provinces

Posking New Ground In Housing Delivery houses, ecurity shows the state of the state



Objectives of the study

O Powing New Ground in Housing Delivery houses, security and control of the security and the Housing Delivery houses, and the Housing Delivery house house he had the Housing Delivery house he had the h o investigate beneficiary information in terms of:

 The name and identify number of the occupant (Head of household) for verification purposes against the National Housing Subsidy System

If the occupant is not the approved beneficiary reflected on the National Housing Subsidy System, how was the relevant house acquired

If the house was sold to the current occupant, what acquiring method was utilized

 The number of properties that have been erroneously allocated;

 The number of properties that are owned by illegal occupants;

 Number of properties that also host small business activities



Posting New Ground In Housing Delivery houses, security and the security a

Objectives of the study

To investigate property information in terms of:

- Location of property
- Physical address
- Street name if applicable;
- Township or village name
- District of location;
- Province of location;
- Recording of site as per Provincial Government register/ or HSS;
- Structure on property
- Physical or structural condition of the house, i.e. its habitability;
- If house/structure is severely defective, its conditions will be described, including digital pictures thereof.



Objectives of the study

Objectives of the study

was anticipated that the report will reveal the following:

- Confirm or dispute HSS beneficiary information when matched against Deeds records of physical verification of actual residents in RDP/BNG houses
- Highlight the degree and extent of reliability and validity of HSS and Deeds records in respect to RDP/BNG houses and their allocation to beneficiaries
- Reveal the number and percentage of beneficiaries who are in HSS records with houses allocated to them, yet they have not yet been allocated the houses.
- Reveal the number and percentage of people who have houses without title deeds.



Objectives of the study

Reaking New Ground The findings should assist the Department to consider important decisions, including the following:

- Regularization process match beneficiaries in the house and the title deeds
- Rectification repairing of defective houses
- Rationalization possibly relocating improperly allocated beneficiaries to their rightful houses
- Reliability ensuring that National Housing records are reliable and dependable
- Replicability ensuring that RSA housing allocation policy is marketed in other countries as best practice for possible replication and adaptation to these countries.



Methodology.....

- The study population comprised the total beneficiaries of houses constructed and completed between 1994 and June 2008 in 7 Provinces of North West; Mpumalanga, Free State, Western Cape, Gauteng, Limpopo, Kwa Zulu Natal.
 - The sample size consisted of 10% of the total population representing 262 686 households
 - ☐ Data collection technique: door to door visit to beneficiaries
 - ☐ Structured questionnaires administered to all beneficiaries who acquired a subsidized house



Methodology.....

- Data Analysis: SPSS data analysis software utilised
- Hoaking New Ground In Housing Delivery houses security and the security an **Quality Control:**
 - ☐ Training of field workers
 - ☐ Field supervisors
 - □ Data cleaning done on questionnaires and coded
 - Limitations of study
 - ☐ Information obtained based on respondents self-declarations
 - ☐ Occupants reluctant to provide personal details
 - ☐ Councillors involved in elections



Free State

ITEM	PERCENTAGE				
Legal Occupant	30				
Renting	4.2				
Purchase	3.0				
Registered title deed	69.2				
Valid ID	99.8				
Habitable (none or minor defects)	72.1				
Not Habitable (major defects)	27.9				

By Houses, security of the Mew Ground In Housing Delivery houses,



North West

ITEM	PERCENTAGE				
Legal Occupant	26				
Renting	4.2				
Purchase	3.0				
Registered title deed	30.8				
Valid ID	99.5				
Habitable (none or minor defects)	78.1				
Not Habitable (major defects)	19.5				

A houses, security supposed the strong delivery houses, security supposed to the stron



Mpumalanga

ITEM	PERCENTAGE				
Legal Occupant	19				
Renting	5.4				
Purchase	2.6				
Registered title deed	22.3				
Valid ID	99.5				
Habitable (none or minor defects)	69.0				
Not Habitable (major defects)	26.6				

A Rew Ground In Housing Delivery houses, security of the strong of the s



Gauteng

ITEM	PERCENTAGE			
Legal Occupant	30.5			
Renting	5.5			
Purchase	3.9			
Valid ID	97.5			
Habitable (none or minor defects)	89.2			
Not Habitable (major defects)	1.7			

By Houses, security of the Mew Ground In Housing Delivery houses,



Western Cape

ITEM	PERCENTAGE			
Legal Occupant	23.8			
Renting	8.4			
Purchase	6.1			
Valid ID	98.8			
Habitable (none or minor defects)	97.8			
Not Habitable (major defects)	0.2			

By Houses, security of the Mew Ground In Housing Delivery houses,



KwaZulu-Natal

ITEM	PERCENTAGE			
Legal Occupant	52.5			
Renting	5.3			
Purchase	5.9			
Valid ID	99.2			
Habitable (none or minor defects)	97.1			
Not Habitable (major defects)	2.9			

A houses, security supported the Housing Delivery houses, security supported to the Housing Delivery houses,



Limpopo

ITEM	PERCENTAGE				
Legal Occupant	55.8				
Care Taker Occupant	14.4				
Dependant	9.7				
Second Owner	11.9				
Unoccupied	2.9				
Not built	8.4				
Habitable (none or minor defects)	82.9				
Not Habitable (major defects)	17.1				

By Houses, security of the Mew Ground In Housing Delivery houses,



By Houses, security and the Housing Delivery house house houses, security and the Housing Delivery house house hou

COMPARISON OF PROVINCES

ITEM	FS	NW	MP	GT	WC	KZN	LP
Legal Occupant	30.3	26.0	19.0	30.5	23.8	52.5	55.8
Renting	4.2	4.2	5.4	5.5	8.4	5.3	0
Purchase	3.0	3.0	2.6	3.9	6.1	5.9	0.0045
Registered title deed	69.2	30.8	22.3	N/A	N/A	N/A	N/A
Valid ID	99.8	99.5	99.5	97.5	98.8	99.2	97.1
Habitable	72.1	78.1	69.0	89.2	97.8	97.1	82.9
Not Habitable	27.9	19.5	26.6	1.7	0.2	2.9	17.1




Posting New Ground In Housing Delivery houses, security and the security a

CONCLUSIONS

- Beneficiary Administration Process:
 - Not performing as expected
 - High percentage illegal beneficiaries in FS, MP and NW
 - Not sound, impartial allocation of houses
 - Official waiting list crucial
 - Important application of waiting list fair and above suspicion
 - Important traditional leadership part of process




LEGAL OCCUPANTS






RENTING






PURCHASE






REGISTERED TITLE






VALID ID





Areaking New Grou


HABITABLE (None or minor defects)





Areaking New Grou

NOT HABITABLE (Major defects)





**Reaking New Ground In Housing Delivery houses, security and

CONCLUSIONS/ continues......

- Quality of subsidised houses:
 - FS highest percentage of houses with major defects
 - Inspection of construction crucial
 - NHBRC ability questioned
 - Inspection capacity to be enhanced with necessary skills
 - Effective enforcement of norms and standards
 - National Department in process to investigate feasibility of National Inspectorate
 - Conveyance process to be revisited
 - Provincial planning processes to be enhanced
- Profile of Beneficiaries:
 - Female and single with dependents
 - SA Citizens





LESSONS LEARNED

Introductory meetings with councilors crucial Planning to be done carefully - community to be informed

Households mainly available over weekends Perception of interviewees can distort outcome



RECOMMENDATIONS

- Initiate a process to match occupants and properties on National Housing Subsidy Database
 - Coordinates to be incorporated in GIS System
- Occupants that acquire properties through inheritance to be regularise
- Task Team to be appointed to investigate beneficiary allocation process and draft implementation guidelines to ensure completed units are allocated to correct beneficiaries
- Determine progress with compilation of official waiting lists in Municipalities
- Possible legislation for implementation of waiting list
- Home ownership course as pre-requisite for housing subsidy – rights in terms of property ownership

Posking New Ground In Housing Delivery houses, security and the security a



CURRENT STATUS

 Verification of data collected by Service Providers

Meetings being arranged with Provincial Human Settlements Departments to compare records and identify problem areas beneficiary administration process

Service providers to be appointed to conduct beneficiary occupancy audit in the EC and NC

Ashing New Ground In Housing Divery houses, security and the security and

